RCRA OUTREACH & DATA VERIFICATION SITE VISIT CHECKLIST						
Site visited by: Jim Lynch, NOWCC/SEE on:		6-21-06		(date of visit)		
EPA RCRA ID#:	IAR000506105	NAICS Code	48821			
Facility Name: Facility Address Phone No.	Relco Locomotive 1 Relco Way 641-932-3030	City, Albia St,Zip IA 52531				
1. Facility Description:		This facility services rail road locomotives.				
2. What Chemical and/or Industrial Waste (CIW) streams are generated? (List name/type, approx amount generated/mo, final disposition/how disposed)		The general industrial waste generated by this facility is sent to the local land fill including air dried spent paint booth filters. The major waste streams are spent paint related material, spent parts washer solvent and used oil. At this time spent paint related material will be taken off site by Coleman of Burlington, IA, used oil is taken off site by Valley Evironmental of Burlington, IA. The two (2) part washer units are serviced by Pollution Control Industries of East Chicago, IN. At this time the water and sludge from a pressure washing unit are being tested for regulated hazardous material.				
3. Does the facility classify any of their CIW's as hazardous waste (HW) (Specify which)		Yes _X_ No This facility classifies the spent paint related material and spent parts washer solvent as regulated hazardous waste.				
4. Does the facility conduct any of the following onsite activities: Treatment/Recycling/Burning/Open Dumping/ Landfills/Surface Impoundments? Describe:		None of these activities are conducted at this facility.				
5. Are CIW/HW stored on-site? Describe (material, approx quantity, storage method):		Yes _X_ No In an above ground metal tank within a secondary containment was app. 1,000 gal of used oil.				
6. Describe condition of storage containers/tanks (open, damaged, unlabeled, leaking, etc.):			The storage container was closed with no damage or leakage and labeled.			
7. Are incompatibles stored solvents, cyanides)? Descri		Yes1	No _X_			
8. Are there any signs of passtressed vegetation, ground of Describe:	-	Yes1	No <u>X</u>	470126		
9. Do any of the on-site cher management practices conce		Yes1	No _X_			

20 JUL 2006 18 Tr. Cor

10. Recommendations and/or Additional Observations:	Used oil should be added to the regulated activity of this site.

(Provided to Jim Lynch on 11/6/95)

CAV Date of Last Revision 6/23/03

Facility Name Aslan Locompline						
Facility Address Aller May Aller 24 5 2 5 3 1						
Inspector (print)						
James L. Lynch						
U.S. EPA, Region VII, 901 N. 5th St., Kansas City, KS 66101	Date 6/31/36					
The United States Environmental Protection Agency (EPA) is obligated, under the Freedom of Information Act, to release information collected during inspections to persons who submit requests for that information. The Freedom of Information Act does, however, have provisions that allow EPA to withhold certain confidential business information from public disclosure. To claim protection for information gathered during this inspection you must request that the information be held CONFIDENTIAL and <u>substantiate</u> your claim in writing by demonstrating that the information meets the requirements in 40 CFR 2, Subpart B. The following criteria in Subpart B must be met: 1. Your company has taken measures to protect the confidentiality of the information, and it intends to continue						
to take such measures.No statute specifically requires disclosure of the information.						
3. Disclosure of the information would cause substantial harm to your company's	s competitive position					
Information that you claim confidential will be held as such pending a determination of	f applicability by EPA.					
I have received this Notice and <u>DO NOT</u> want to make a claim of confidentiality at this time.						
Facility Representative Provided Notice (print) Signature	e/Date					
Kink DATWYHA. KI Bal	Turk 6/21/04					
I have received this Notice and <u>DO</u> want to make a claim of confidentiality.						
Facility Representative Provided Notice (print) Signature	e/Date					
Information for which confidential treatment is requested;						
	e e					

(Rev: 11/15/99)

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY RECEIPT FOR DOCUMENTS AND SAMPLES

Facility Name Roumatine
Facility Address / Refer Way 3263/
Documents Collected? YES (list below) NO
Samples Collected? YES (list below) NO Split Samples: YES NO
Documents/Samples were: 1)Received no charge2)Borrowed3)Purchased
Amount Paid: \$ Method: Cash Voucher To Be Billed
The documents and samples described below were collected in connection with the administration and enforcement of the applicable statute under which the information is obtained.
Receipt for the document(s) and/or sample(s) described below is hereby acknowledged:
Imanifest I page
Facility Representative (print) Signature/Date
Kiek DATWyler Water
Inspector (print) Signature/Date
U.S. EPA, Region VII, 901 N. 5th Street, Kansas City, KS 66101
(rev:1/20/93)

3

8354985/ 502892

Emergency Contact Telephone Number Please print or type [Form designed for use on eithe (12-pitch) typewriter.) Form Approved				A DEP STORY		000012					
ľ	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. I · A · R · 0 · 0 · 0 · 5 · 0 · 6 · 1 · 0 · 5	Manifest Document No. 3 · 2 · 7 · 0 · 6	2. Page 1	Information		naded areas is eral law.				
1	Generator's Name and Mailing Address RELCO LOCOMOTIVE RELCOWAY ALRIA IA 52531	Generator's Name and Mailing Address RELCO LOCOMOTIVE 1 RELCOWAY ALBIA_1A_52531					A. State Manifest Document Number 32.706 I N B. State Generator's ID OHUPW-06191				
Name of Street, or	Transporter 1 Company Name Alpont Transportation, LLC Transporter 2 Company Name	6. US EPAID N P.A.R.O.O.O.5 8. US EPAID N	US EPA ID Number .A.R.0.0.0.5.0.4.9.4.4 US EPA ID Number			C. State Transporter's ID D. Transporter's Phone /24 981-3771 E. State Transporter's ID F. Transporter's Phone					
	Designated Facility Name and Site Address POLLUTION CONTROL INDUSTRIES 4343 KENNEDY AVENUE	10. US EPA ID N	umber	G. State Fa	acility's ID						
	EAST CHICAGO IN 46312 11. US DOT Description (Including Proper Shipping	Name, Hazard Class, and ID Number)	.4.8.9.4.3 12. Cont	ainers Type	13. Total Quantity	7-3951 14. Unit Wt/Vol	I. Waste No.				
	a. RQ, Waste Paint Related Material 3, UN1263, II		00.4	DM .	. 55	G	D001 F003 F005				
GENERATOR	с.										
TOR	d.										
	J. Additional Descriptions for Materials Listed Above				Codes for Wa	stes Lister	d Above				
	a) (I,T) STREAM# 293410 ERG#128				501						
	15. Special Handling Instructions and Additional Information 2.4 HOUR EMERGENCY PHONE: INFOTRAC 800-535-5053 RELCO: 641-932-3521 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimized the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is										
¥	available to me and that I can afford. Printed/Typed Name DAVIO ADLER	Signature	()			Moi O	nth Day Year 3 2.70.6				
-RANSPORTER	Transporter 1 Acknowledgement of Receipt of Mis Printed/Typed Name True Bot 18. Transporter 2 Acknowledgement of Receipt of Mis	Signature	Self	_		Moi	nth Day Year 3 2.706				
NH HE	Printed/Typed Name	Signature				Mor	nth Day Year				
FACIL		Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Signature A Month						nth Day Year					
Lisa Droegeneier Lisa Avolgeneier 03/31/06.											
Denoting also OTNIARIGNAL — RETURN TO GENERATOR (Rev. 504)											

HANDLER INFORMATION REPORT

PROCEDURES for Inspectors/Investigators/etc. performing Site Visits

Present the Facility representative with a copy of their:

Handler Information Report (attached)

- Copy of the current Notification Form (attached)
- Copy of the current Notification Booklet (attached)

Our instructions to them are printed on their Handler Information Report - and should be self explanatory. If the facility wants to revise their Handler Information Report, they can do so and mail it back to EPA - or have the inspector deliver it.

If during the course of the site visit, the inspector/investigator becomes aware of any changes which should be made to the information printed on this form, please make the corrections and return the form to: Lisa Haugen, ARTD/RESP.

EPA RCRA ID Number:

IAR000506105

Name of Company/Site:

Location of Site:

RELCO LOCOMOTIVE 1 RELCO WAY ALBIA, IA 52531 MONROE County

Land Type:

Private

NAICS:

48821 - Support Activities for Rail Transportation

Mailing Address:

1 RELCO WAY ALBIA, IA 52531

Site Contact: Phone Number: Address:

DETWILLER KURT (641) 932-3030 1 RELCO WAY ALBIA, IA 52531

Current Owner of Site:

RELCO LAND HOLDINGS OF IOWA

Owner Type:

Private

Current Operator of Site:

RELCO LOCOMOTIVE

Operator Type:

Private

TYPE(S) OF REGULATED ACTIVITY:

Federal Small Quantity Generator

Hazardous Wastes Handled:

Certified by Notification

N 03/22/06 2

on 03/22/06 by

D001

DONALD L BACHMAN 03/22/06


CEO

Date of Site Visit: Name of Inspector (Please print): _ ☐ EBA R7 ENSV ☐ EPA R7 Contractor ☐ NOW CC/SEE Investigator (Check one): Signature of Inspector.

IAR000506105 Relco Locomotive, Albia, IA Photos taken: 6-21-06 Photo #1 One of two parts washer units.



IAR000506105 Relco Locomotive, Albia, IA Photos taken: 6-21-06 Photo #2 Metal above ground tank containing used oil within secondary containment.




IAR000506105

Relco Locomotive, Albia, IA Photos taken: 6-21-06 Photo #3 Power washer drain.



IAR000506105 Relco Locomotive, Albia, IA Photos taken: 6-21-06 Photo #4 Paint booth with wall filters.



IAR000506105 Relco Locomotive, Albia, IA Photos taken: 6-21-06 Photo #5 Main entrance to the site.

